



Canyon Fuel Company
SUFCO Mine
397 South 800 West
Salina, UT 84654
(435) 286-4880 Fax (435) 286-4499

March 14, 2001

Ms. Kelly Coleman
Department of Environmental Quality
Division of Water Quality
288 North 1460 West
P. O. Box 144870
Salt Lake City, UT 84114-4870

[Handwritten signature]
2/04/002

Dear Ms. Coleman:

Enclosed are the February 2001, Discharge Monitoring Reports (DMR's) for the SUFCO Mine facility, permit number UT-0022918. Discharge point 001A had no outflow. As previously reported the TSS threshold was exceeded at point 002A on February 7, 2001 while decanting the sediment pond during snow melt. No SS test was done on that date even though snow melt conditions existed. The February 21, 2001 sample also exceeded the TSS threshold, but the SS value was less than 0.1. The SS threshold is 0.5 during snow melt conditions which were applicable. The outflow from point 003A had no exceedances for the month.

The acute biomonitoring for point 003A was successfully passed using ceriodaphnia during February.

Sincerely,
CANYON FUEL COMPANY, LLC
SUFCO Mine

[Handwritten signature of Wesley K. Sorensen]

Wesley K. Sorensen, P.E.
Technical Services Manager

WKS:kb

Encl.: February DMR's

cc: Mary Ann Wright, DOGM
Guy Pence, USFS Fishlake
Chris Hansen, Skyline
Compliance Officer, U.S. EPA, Denver
EPA Test Procedures & Water Monitoring File